IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re: Paatero

U.S. Patent No.: 7,684,222

Application No.: 10/808,007

Issued: March 23, 2010 Confirmation No: 5679

Filed: March 24, 2004

Title: Power Conversion Apparatus with DC Bus Precharge Circuits and Methods of Operation

Thereof

August 3, 2010

Commissioner for Patents

Attn: Certificate of Correction Branch

P.O. Box 1450

Alexandria, VA 22313-1450

REQUEST FOR ENTRY OF CERTIFICATE OF CORRECTION UNDER No. 35 U.S.C. \$254 AND 37 C.F.R. \$1.322

Sir:

The Assignee of record for the above-referenced patent hereby requests, pursuant to 35 U.S.C. §254 and 37 C.F.R. §1.322, that a Certificate of Correction be issued. This request is made in order to correct the mistakes incurred through the fault of the U.S. Patent and Trademark Office. The mistakes appearing in the patent are set forth with corrections on the Certificate of Correction attached herewith.

No fee is believed due. However, the Commissioner is authorized to charge any deficiency or credit any overpayment to Deposit Aecount No. 50-0220.

> Robert M. Meeks Registration No.: 40,723

Myers Bigel Sibley & Sajovec, P.A. P. O. Box 37428, Raleigh, NC 27627

Telephone: (919) 854-1400 Facsimile: (919) 854-1401

Customer No. 20792

CERTIFICATION OF ELECTRONIC TRANSMISSION

I hereby certify that this correspondence is being transmitted via the Office electronic filing system in accordance with § 1.6(a)(4) to the U.S. Patent and Trademark Office on August 3, 2010.

Lanie A. Dobson

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 1 of 1

PATENT NO.: 7,684,222

APPLICATION NO.: 10/808,007

ISSUE DATE: March 23, 2010

INVENTOR(S): Paatero

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the Claims:

Column 10, Claim 35, Line 38: Please correct "claim)5" to read -- claim 25 -- Claim 40, Line 65: Please correct "capacitance and" to read

-- capacitance; and --

Column 11: Claim 44, Line 24: Please correct "voltage and" to read -- voltage; and --